



Village of Menomonee Falls
W156 N8480 Pilgrim Road
Menomonee Falls, WI 53051-3140
Telephone: (262) 532-4200

STORMWATER MANAGEMENT FACILITIES OPERATION AND INSPECTION REPORT

Quarter Section
Property Tax ID Number

NW1/4 S. 30 Name of Business/Subdivision
MNFV01189 Address of Property
9701

Silver Spring Estates Phase II
Legacy Trail, Menomonee Falls, WI

Date Oct. 16, 2020

350' East of the intersection of
Masters Drive and Legacy Trail.

Dry Pond		Pond ID: SWP30N003	Location of Pond
Wet Pond	X		
Other			PCP 2015-06

Year Pond
Constructed

2015

Year of Last
Certification

2015

Compliance Verification	Design	Actual	Compliant Yes	Comments (Condition of Structure)
Primary Outlet Pipe				
Opening Diameter (inches)	24"	24"	x	RCP pipe outlet discharges to Phase I pond via the storm sewer system in Legacy Trail.
Upstream Invert	854.50'	854.54'	x	Observed no obstructions or concerns when inspection discharge piping.
Downstream Invert	854.29	854.32	x	
Length (feet)	63.7'	64'	x	Discharge to Storm Sewer System, no changes since original certification and storm sewer as built.
Slope (%)	.33%	.33%	x	
Secondary Outlet Pipe	(If Applicable)			
Opening Diameter (inches)	24"	24"		Outlet Pipe Material
Upstream Invert	856.17'	856.09'	x	RCP
Downstream Invert	855.0'	854.87'	x	
Length (feet)	166'	163'	x	Minor Changes since as built due to minor settlement or placement of survey shot.
Slope (%)	0.70%	0.74%	x	No concerns.
Riser	(If Applicable)			
Opening Diameter (inches)	48"	48"	x	Riser Material
Elevation	859.42'	859.44'	x	48" DIA precast MH structure with trash rack. All ok no issues. (See pictures)
Upper Discharge Control	(If Applicable)			
Opening Diameter (inches)	12.5"	12.5"	x	Clear cattails away from all orifices and keep free of trash and debris.
Elevation	855.90'	855.85'	x	

Compliance Verification	Design	Actual	Compliant Yes No	Comments			
Lower Discharge Control	(If Applicable)						
Opening Diameter (inches)	6"	6"	x	x	6" Orifice buried by rock, confirmed from inside of structure.		
Elevation	854.50'	854.54'	x				
Other (Description)							
Opening Type and Size (inches)	48"	48"	x	x			
Elevation	860.30'	860.21'	x				
Emergency Spillway							
Elevation	NA	NA			No traditional Spillway was designed. Secondary riser overflow shall serve as the emergency conveyance with spillway below.		
Length of spillway (feet)	NA	NA					
Embankment	Present Yes no		Comments/Maintenance Requirements				
Unauthorized Plantings, trees, or woody vegetation	X		Some willow type trees present along banks should be removed. Cattail vegetation growing is acceptable but should be removed at all inlet and outlet pipes to allow for proper flow into and out of the pond.				
Animal burrows or slope erosion		X					
Storm Sewer Outfalls	Type & Size		Location	Comments			
Outfall 1	24" RCP		SW Corner	Remove Cattails from in front of outfall			
Outfall 2	24" RCP		SW Corner on west side bump out	Remove Cattails from in front of outfall			
Outfall 3	24" RCP		West side bump out	Remove Cattails from in front of outfall			
Outfall 4	36" RCP		NW Corner on west side bump out	Remove Cattails from in front of outfall			
Outfall 5	30" RCP		North side	Remove Cattails from in front of outfall			
Outfall 6	36" RCP		SE corner	Remove Cattails from in front of outfall			
Outfall 7	18" RCP		South side	Remove Cattails from in front of outfall			

Storage Properties	Design	Actual	Compliant		Not Applicable	Equipment Used
			Yes	No		
Normal Water Elevation (Wet Ponds)	854.50'	854.54'	x			Points surveyed with robotic total station. Underwater points Surveyed with Total station while paddling a John Boat. 9-23-20 Storage calculated using surveyed elevations and areas, previous as built was calculated with Water Cadd modeling software.
Design High Water Elevation	861.20'	861.21'	x			
Area at Normal Water Elevation (Ac) (Wet Ponds)	1.46 ac	1.43 ac	x			
Area at Design High Water Elevation (Ac)	1.98ac	2.05 ac	x			
Active Storage Available (Ac-Ft)*	10.56af	10.98 af				
Lowest Elevation at Top of Embankment (If Applicable)	861.5'	861.54'	x			
Average Elevation at Top of Embankment (If Applicable)	861.5'	861.60'	x			
Maximum Bottom Elevation	846.0'	845.81'	x			
Average Pond Bottom Elevation	846.0'	845.99'	x			
Pond Bottom Area (Ac)						
Maximum Pond Depth	8.5'	8.73'	x			
Average Pond Depth	8.5'	8.55'	x			
Average Permanent Pool Depth (Wet Ponds)	8.5'	8.55'	x			

*To Determine Active Storage $V=H/3(A1+A2+(A1xA2)1/2)$

Wet Ponds Use H = Height of Section , $A1$ = area at normal water elevation, $A2$ =area at top section

Dry Ponds Use H = Height of Section, $A1$ = pond bottom area, $A2$ =area at top section

<p><i>Sketch Outlet or Attach to Document</i></p> <p><i>**Pond exhibit survey from 9-23-2020 attached. Note all areas above water surveyed and represented on this document. Areas below water checked in random locations as shown on the exhibit. Full topography below water surface was not completed for this certification.</i></p> <p><i>** A copy of the original pond detail page has also been attached for reference.</i></p>	<p><i>Place Photograph of Pond or Attach to Document</i></p>
--	--

Place Photograph of Pond or Attach to Document

Attach As-built Survey to the Document for the first report submission

Inspection Firm: Excel Engineering Inc.
Phone Number: 920-926-9800
Address: 100 Camelot Drive
Fond du lac, WI 54935

Inspector Name : Max Franzen
Inspection Date: 10/16/20


Certifying Professional Grant Duchac, P.E.
Name: _____
Phone Number: 920-926-9800


Date: 10/29/20

Signature: 




10-3-2012


GRADING AS BUILT
POND





STORM MANHOLE/FIELD INLET DETAIL

NO SCA




SANITARY MANHOLE DETAIL

NO SCARS




CURB INLET

NO SCALE




CLAY LINED RETENTION POND DETAIL

NO SCAR



GALVANIZED TRASH RACK DETAIL

NO SC



OUTLET/OVERFLOW STRUCTURE DETAIL

NO SCALE

Photos Phase II Pond Cert 9-23-20

Prepared by : Max FRANZEN

Oct 19, 2020



IMG_6496

Taken on:
Sep 23, 2020 10:39 AM



IMG_6495

Taken on:
Sep 23, 2020 10:39 AM



IMG_6494

Taken on:
Sep 23, 2020 10:39 AM



IMG_6491

Taken on:
Sep 23, 2020 10:38 AM



IMG_6490

Taken on:

Sep 23, 2020 10:38 AM



IMG_6489

Taken on:

Sep 23, 2020 10:19 AM



IMG_6487

Taken on:

Sep 23, 2020 10:19 AM



IMG_6486

Taken on:

Sep 23, 2020 10:18 AM



IMG_6485

Taken on:

Sep 23, 2020 10:18 AM



IMG_6484

Taken on:

Sep 23, 2020 10:18 AM



IMG_6483

Taken on:

Sep 23, 2020 10:18 AM



IMG_6482

Taken on:

Sep 23, 2020 10:18 AM



IMG_6481

Taken on:

Sep 23, 2020 10:18 AM



IMG_6480

Taken on:

Sep 23, 2020 10:14 AM



IMG_6479

Taken on:

Sep 23, 2020 10:14 AM



IMG_6478

Taken on:

Sep 23, 2020 10:14 AM



IMG_6477

Taken on:

Sep 23, 2020 10:14 AM



IMG_6476

Taken on:

Sep 23, 2020 10:13 AM



IMG_6475

Taken on:

Sep 23, 2020 10:13 AM



IMG_6474

Taken on:

Sep 23, 2020 10:13 AM



IMG_6473

Taken on:

Sep 23, 2020 10:13 AM



IMG_6472

Taken on:

Sep 23, 2020 10:09 AM



IMG_6471

Taken on:

Sep 23, 2020 10:09 AM



IMG_6470

Taken on:

Sep 23, 2020 10:09 AM



IMG_6469

Taken on:

Sep 23, 2020 10:08 AM



IMG_6468

Taken on:

Sep 23, 2020 10:08 AM



IMG_6466

Taken on:

Sep 23, 2020 10:08 AM



IMG_6467

Taken on:

Sep 23, 2020 10:08 AM



IMG_6465

Taken on:

Sep 23, 2020 10:08 AM



IMG_6464

Taken on:

Sep 23, 2020 10:08 AM



IMG_6462

Taken on:

Sep 23, 2020 10:05 AM



IMG_6461

Taken on:

Sep 23, 2020 10:05 AM



IMG_6459

Taken on:

Sep 23, 2020 10:05 AM



IMG_6460

Taken on:

Sep 23, 2020 10:05 AM



IMG_6458

Taken on:

Sep 23, 2020 10:05 AM



IMG_6457

Taken on:

Sep 23, 2020 10:05 AM