



Village of Menomonee Falls
W156 N8480 Pilgrim Road
Menomonee Falls, WI 53051-3140
Telephone: (262) 532-4200

STORMWATER MANAGEMENT FACILITIES OPERATION AND INSPECTION REPORT

Quarter Section SE 1/4 Sec. Name of Business/Subdivision Heritage Reserve Holdings, LLC
13-8-20
 Property Tax ID Number MNFV00519
4002 &
MNFV00519
44052 Address of Property Heritage Reserve
 Date 5/29/2015

Dry Pond	
Wet Pond	X
Other	

Location of Pond Southeast Portion of
MNFV005194002 and Southwest
Portion of MNFV0051944052
 Pond ID: SWP13S005 &
SWP13S007

Year Pond Constructed 2005 Year of Last Certification 2014 Design data based on Stantec Memo dated August 5, 2014, File No. 1938990300

Compliance Verification	Design	Actual	Compliant Yes No	Comments (Condition of Structure)
Primary Outlet Pipe				Outlet Pipe Material
Opening Diameter (inches)	30"	24"		Physically SWP13S005 and SWP13s007 are two separate ponds, but when design was modeled as one pond, with a 5' x 5' equalization pipe between the ponds. Surveyed Dimensions of equalization pipe are as follows: Upstream Invert: 764.27 Downstream Invert: 764.09 Length: 50' Slope: 3.6%
Upstream Invert	765.47	765.20		
Downstream Invert	764.67	764.73		
Length (feet)	66.4	63'		
Slope (%)	1.20%	0.75%		
Secondary Outlet Pipe	(If Applicable)			Outlet Pipe Material
Opening Diameter (inches)				
Upstream Invert				
Downstream Invert				
Length (feet)				
Slope (%)				
Riser	(If Applicable)			Riser Material
Opening Diameter (inches)				
Elevation				
Upper Discharge Control	(If Applicable)			
Opening Diameter (inches)	4"	4"		
Elevation	766.94	766.86		


Compliance Verification	Design	Actual	Compliant Yes No		Comments	
Lower Discharge Control	(If Applicable)					
Opening Diameter (inches)	6"	6"				
Elevation	765.50	765.20				
Other (Description)						
Opening Type and Size (inches)	_____	_____				
Elevation	_____	_____				
Emergency Spillway						
Elevation	770.50	770.44				
Length of spillway (feet)	25'	10'				
Embankment	Present Yes No		Comments/Maintenance Requirements			
Unauthorized Plantings, trees, or woody vegetation		X				
Animal burrows or slope erosion		X				
Storm Sewer Outfalls	Type & Size		Location		Comments	
Outfall 1	RCP 24"		North portion of pond		See Figure 4 in attached Photo Document. Seen in the figure is debris and vegetation around. Recommend the debris be removed.	
Outfall 2	RCP 18"		East portion of pond			
Outfall 3	RCP 18"		Southeast portion of pond			
Storage Properties	Design	Actual 005/007	Compliant Yes No		Not Applicable	Equipment Used
Normal Water Elevation (Wet Ponds)	765.50	763.90/763.70	X			Trimble R6 GPS HWL Calculated by HydroCAD
Design High Water Elevation	769.86	769.35	X			
Area at Normal Water Elevation (Ac) (Wet Ponds)	0.678	0.480 Combined	X			Area at HWL Calculated by HydroCAD
Area at Design High Water Elevation (Ac)	1.169	1.048	X			
Active Storage Available (Ac-Ft)*	5.993	5.992	X			Trimble R6 GPS
Lowest Elevation at Top of Embankment (If Applicable)	770.50	770.44	X			Lowest Bottom Elevation
Average Elevation at Top of Embankment (If Applicable)	771.50	771.75	X			
Maximum Bottom Elevation	759.00	759.56/757.90				
Average Pond Bottom Elevation	759.00	760.00/758.00				
Pond Bottom Area (Ac)	0.24	0.078 Combined				
Maximum Pond Depth	11.5	12.19'/13.85'				
Average Pond Depth	11.5	11.75'/13.75'				
Average Permanent Pool Depth (Wet Ponds)	6.5	3.9'/5.7'				

*To Determine Active Storage $V=H/3(A1+A2+(A1 \times A2)/2)$


Wet Ponds Use H = Height of Section , $A1$ = area at normal water elevation, $A2$ =area at top section

Dry Ponds Use H = Height of Section, A_1 = pond bottom area, A_2 =area at top section

Outlet Sketch



See Attached Photo Document



See Attached Photo Document

Attach As-built Survey to the Document for the first report submission

Inspection Firm:	<u>JSD Professional Services, Inc</u>	Inspector Name :	<u>Ryder Fischer</u>
Phone Number:	<u>(262) 513-0666</u>	Inspection Date:	<u>5/29/15</u>
Address:	<u>N22 W22931 Nancys Ct.</u>		
	<u>Suite 3</u>		
	<u>Waukesha, WI 53186</u>		

Certifying
Professional Name: Rizal Iskandarsjach P.L.S., P.E.
Phone Number: (262) 513-0666



Date: <u>7/31/15</u>	Signature: <u>Rizal Iskandarsjach</u>
-------------------------	--



Figure 1: Overview of the Pond Looking in the Northeast Direction



Figure 2: Image of the Equalization Structure



Figure 3: Photo of the Retaining Wall Looking South



**Figure 4: North 24" RCP
(Outfall the debris)**



Figure 5: East 18" RCP Outfall



Figure 6: Southeast 18" RCP Outfall



Figure 1- Overview of Pond Looking Southwest



Figure 2- Overview of Pond Looking Northeast



Figure 3- View of the Outlet Structure



Figure 4- Image of the Interior of the Outlet Structure



Figure 5- Equalization Pipe between SWP13S007 and SWP13S005



Figure 6- Photo of Retaining Wall Looking South