

2008 file

Dec 7/30/13

Village of Menomonee Falls  
W156 N8480 Pilgrim Road  
Menomonee Falls, WI 53051-3140  
Telephone: (262) 532-4200

**STORMWATER MANAGEMENT FACILITIES  
OPERATION AND INSPECTION REPORT  
POUROUS PAVEMENT**

Quarter Section SW 1/4 Sec 26 Name of Business/Subdivision Shecterle Commercial Properties 6  
Property Tax ID Number 0103-983 Address of Property PO Box 1205  
Brookfield, WI 53005

Location of Device North parking area in front of Building A & future Building B  
Year Constructed 2008 Last Certification Q1 2013

Owner Change since last inspection? Y N  
Owner Name, Address, Phone: Brian Shecterle, (262) 227-9032

Date: 07/09/2013 Time: 10:00AM Site conditions: 65 F and Cloudy

Inspection Items	Satisfactory (S) or Unsatisfactory (U)	Comments/Corrective Action
Signs of clogging (e.g., standing water)?	S	Several sections of pavement were replaced after being found out of specification at the time of placement. No standing water found in low areas.
Debris (mulch, trash) accumulation?	S	None observed.
Sediment accumulation?	S	No environmental sediment present in low areas. Continue with routine sweeping.
Standing water?	S	None observed.
Erosion from underdrain (if present)?	S	Not visible from surface.
Exposed soil in areas discharging or adjacent to the porous pavement area?	S	All landscaped areas are stable with decorative rock used in planting beds.
Runoff discharge from pavement area 24 to 48 hours after the end of a storm event?	S	No ponding observed by owner or tenants at this time.
Snow Removal Practices?	S	Salt being used exclusively during snow removal operations. Continue with salting and plowing only.
Other (describe)?		
<b>Hazards</b>		
Have there been complaints from public?	S	None known.
Public hazards noted?	S	None.

If any of the above inspection items are **UNSATISFACTORY**, list corrective actions and the corresponding completion dates below:

Corrective Action Needed	Due Date
Clean outfall end section of plant debris.	09/01/2013
Open outfall structure and remove any sediment.	09/01/2013

Sketch Outlet  See attached site photo log.	Photograph of Pond  See attached photo log.
	Photograph of Pond  See attached photo log.

Inspection Firm: One Source Consulting  
Phone Number: (262) 781-9005  
Address: 19435 W. Capitol Drive  
Brookfield, WI 53045

Inspector Name: Craig Donze, PE  
Inspection Date: 07/09/2013

Certifying  
Professional Name: Craig Donze, PE  
Phone Number: (262) 781-9005

Date:  
07/09/2013

Signature:  


**Pilgrim Spring Market Place  
POUROUS PAVEMENT – Photo Log**

Photos taken: 07/09/2013 (Last measureable rainfall 07/08/2013.)

Photo #1: South parking field of east parking area looking south.



Photo #2: South parking field of east parking area looking south.



Photo #3: South area of east parking field looking north.



Photo #4: North parking area of west parking field looking west.



Photo #5: Outfall structure with clear storm water discharge.



Village of Menomonee Falls  
W156 N8480 Pilgrim Road  
Menomonee Falls, WI 53051-3140  
Telephone: (262) 532-4200

## POUROUS PAVEMENT

### Maintenance Requirements

Regular inspection and maintenance is critical to the effective use of porous pavement as a storm water best management practice. It is the responsibility of the property owner to maintain all storm water facilities in accordance with the minimum design standards and other guidance provided in this manual. The Village Engineer has the authority to impose additional maintenance requirements where deemed necessary.

This page provides guidance on maintenance activities that are typically required for porous pavement, along with a suggested frequency for each activity. Individual porous pavement applications may have more, or less, frequent maintenance needs, depending upon a variety of factors including traffic loads, the occurrence of large storm events, overly wet or dry (i.e., drought) regional hydrologic conditions, and any changes or redevelopment in the upstream land use. Each property owner shall perform the activities identified below at the frequency needed to maintain porous pavement properly at all times.

Inspection Activity	Suggested Schedule
<ul style="list-style-type: none"><li>• Ensure that the porous pavement surface is free of sediment and debris (e.g., mulch, leaves, trash, etc.).</li><li>• Ensure that the contributing area upstream of the porous pavement surface is free of sediment and debris.</li><li>• Check to make sure that the porous pavement dewateres between storms.</li><li>• Inspect the surface for structural integrity. Inspect for evidence of deterioration or spalling.</li></ul>	As Needed
<b>Maintenance Activities</b>	<b>Suggested Schedule</b>
<ul style="list-style-type: none"><li>• Ensure that contributing area and porous pavement surface are clear of debris (e.g., mulch, leaves, trash, etc.).</li><li>• Ensure that the contributing and adjacent area is stabilized and mowed, with clippings removed.</li><li>• Vacuum sweep porous pavement surface to keep free of sediment.</li><li>• Replace the porous pavement, including the top and base course, as needed.</li></ul>	As needed, based on inspection
	Typically three to four times per year
	Upon failure

The Village of Menomonee Falls encourages the use of the inspection checklist presented below for guidance in the inspection and maintenance of porous pavement. The Director can require the use of this checklist or other form(s) of maintenance documentation when and where deemed necessary in order to ensure the long-term proper operation of the unit. Questions regarding inspection and maintenance should be referred to the The Village of Menomonee Falls Engineering Department.